

Observation Number:	202139664
Originator:	
Date Created:	07-May-2021
Business Unit:	Projects
Business Group:	Process & Chemicals
Project/Office:	Chonburi Office
Sub Business Group:	APAC
Site/Office Name:	Thailand Choburi Office
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	Level 8 - Building U41
Observation Type:	Unsafe Condition
Observer Name:	Glauco Donida
Observer Email Address:	glauco.donida@woodplc.com
Stakeholder:	Contractor
Observation Date:	06-May-2021
Observation Time:	18:30
Observation Close Date:	09-Sep-2021
Observation Category:	Tools and Equipment Safe / unsafe condition
Details of safety observation:	Water leakage from the roof - from Level 8 - from the opening - high risk of the leakage on the electrical cabinets already energized
Immediate action taken:	Remedial action: requested to MAS to install and to cover the opening in the proper way. Official letter sent to Contractor (FNC) that removed the protection without installing back the protection
Supporting Information:	
Feedback required?:	No