

<b>Observation Number:</b>	201903430
<b>Originator:</b>	
<b>Date Created:</b>	28-Feb-2019
<b>Business Unit:</b>	Consulting
<b>Business Group:</b>	Resilient Environments
<b>Project/Office:</b>	RE - East US
<b>Sub Business Group:</b>	Americas
<b>Site/Office Name:</b>	Kennesaw, GA
<b>Work Related or Non-Work Related Observation?:</b>	Non-Work Related
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	Cartersville, GA
<b>Observation Type:</b>	Safe Behaviour
<b>Observer Name:</b>	Jason Muhlbauer
<b>Observer Email Address:</b>	jason.muhlbauer@gmail.com
<b>Stakeholder:</b>	Wood
<b>Observation Date:</b>	28-Feb-2019
<b>Observation Time:</b>	08:30
<b>Observation Close Date:</b>	28-Feb-2019
<b>Observation Category:</b>	Travel and Safety away from the office Transportation
<b>Name of Individual or Team:</b>	Jason Muhlbauer
<b>Details of safety observation:</b>	I noticed a very sharp dip in the road inside my subdivision around a manhole cover. I realized that the asphalt had sunk down about 6 to 8 inches within the past 2 weeks from all of the rain. The depression is clearly revealing eroding ground beneath, possibly even a sinkhole.
<b>Immediate action taken:</b>	I informed my HOA of the unsafe road condition so it doesn't pose a greater future threat.
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No