

<b>Observation Number:</b>	202139664
<b>Originator:</b>	
<b>Date Created:</b>	07-May-2021
<b>Business Unit:</b>	Projects
<b>Business Group:</b>	Process & Chemicals
<b>Project/Office:</b>	Chonburi Office
<b>Sub Business Group:</b>	APAC
<b>Site/Office Name:</b>	Thailand Choburi Office
<b>Work Related or Non-Work Related Observation?:</b>	Work Related
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	Level 8 - Building U41
<b>Observation Type:</b>	Unsafe Condition
<b>Observer Name:</b>	Glauco Donida
<b>Observer Email Address:</b>	glauco.donida@woodplc.com
<b>Stakeholder:</b>	Contractor
<b>Observation Date:</b>	06-May-2021
<b>Observation Time:</b>	18:30
<b>Observation Close Date:</b>	09-Sep-2021
<b>Observation Category:</b>	Tools and Equipment Safe / unsafe condition
<b>Details of safety observation:</b>	Water leakage from the roof - from Level 8 - from the opening - high risk of the leakage on the electrical cabinets already energized
<b>Immediate action taken:</b>	Remedial action: requested to MAS to install and to cover the opening in the proper way. Official letter sent to Contractor (FNC) that removed the protection without installing back the protection
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No