

<b>Observation Number:</b>	201900776
<b>Originator:</b>	
<b>Date Created:</b>	21-Jan-2019
<b>Business Unit:</b>	Projects
<b>Business Group:</b>	Process & Chemicals
<b>Project/Office:</b>	Shell Bukom EFA Projects
<b>Sub Business Group:</b>	APAC
<b>Site/Office Name:</b>	Shell Bukom
<b>Work Related or Non-Work Related Observation?:</b>	Work Related
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	TGU area under pipe rack
<b>Observation Type:</b>	Safe Condition
<b>Observer Name:</b>	Reddy Ashok Vellappa
<b>Observer Email Address:</b>	Ashok.reddy@woodplc.com
<b>Stakeholder:</b>	Contractor
<b>Observation Date:</b>	03-Jan-2019
<b>Observation Time:</b>	02:45
<b>Observation Close Date:</b>	21-Jan-2019
<b>Observation Category:</b>	Contractor Site safety Signage and instructions
<b>Details of safety observation:</b>	All Scaffold tagging and instruction are clear to use it some place required H2S Mask Provided around that area its very use full to claim up and checking and site survey
<b>Immediate action taken:</b>	
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No