

<b>Observation Number:</b>	201900419
<b>Originator:</b>	
<b>Date Created:</b>	11-Jan-2019
<b>Business Unit:</b>	E&I Solutions
<b>Business Group:</b>	Europe
<b>Project/Office:</b>	UK Built Environment
<b>Service Line:</b>	Remediation and Ground Engineering
<b>Site/Office Name:</b>	Shrewsbury (Built Environment)
<b>Work Related or Non-Work Related Observation?:</b>	Work Related
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	Alderbury NGGT site: Drilling BH02
<b>Observation Type:</b>	Unsafe Act
<b>Observer Name:</b>	Lewis Miffling
<b>Observer Email Address:</b>	lewis.miffling@woodplc.com
<b>Stakeholder:</b>	Contractor
<b>Observation Date:</b>	17-Dec-2018
<b>Observation Time:</b>	11:00
<b>Observation Close Date:</b>	18-Jan-2019
<b>Observation Category:</b>	Contractor Site safety Safety awareness & behaviour
<b>Details of safety observation:</b>	Whilst attaching additional rods (3m) to drill string second man stepped up on clamp arm to position rod so it could be attached.
<b>Immediate action taken:</b>	Wood Site Engineer (Sarah Evans) immediately told second man to get down, not to do it again and to revert back to 1.5m rods which can be adjusted, if required, from the ground without the need to step up. Incident was witnessed and recorded by dnvgl site auditor who was satisfied with the actions taken on site
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No