

|   |  |
|---|--|
| <b>Originator:</b>  |  |
| <b>Date Created:</b>  | 09-Jul-2018  |
| <b>Business Unit:</b>   | AS EAAA  |
| <b>Business Group:</b>  | Operations Services Europe & Africa  |
| <b>Project/Office:</b>  | Western Gas Alliance   |
| <b>Service Line:</b>  | Transmission & Distribution  |
| <b>Site/Office Name:</b>  | Western Gas Alliance 1855005/6   |
| <b>Home or Work Related Observation?:</b>                         | Work   |
| <b>Exact Location or Project of Act/Condition/Safe Behaviour:</b> | Maindy Rd Cowbridge  |
| <b>Observation Type:</b>  | Unsafe Act   |
| <b>Observer Name:</b>   | Christopher John   |
| <b>Observer Email Address:</b>                                    | trevor.clark@wwutilities.co.uk   |
| <b>Stakeholder:</b>   | Wood   |
| <b>Observation Date:</b>  | 26-Jan-2018  |
| <b>Observation Time:</b>  | 13:45  |
| <b>Observation Close Date:</b>                                    |  |
| <b>Details of safety observation:</b>                             | Intervention : Team digging out kerbs leant the pick against the wall then noticed it had fallen on the footpath |
| <b>Immediate action taken:</b>                                    | The pick was uplifted straight away and put safe within the barrier system                                       |
| <b>Supporting Information:</b>                                    |  |
| <b>Feedback required?:</b>  | No   |
| <b>Comments from Reviewer</b>                                     |  |
| <b>Cancel Comments:</b>   | Not Wood related   |