

Observation Number:	201809247
Originator:	
Date Created:	03-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	Station inn Nantgarw Road Caerphilly
Observation Type:	Unsafe Condition
Observer Name:	Ian Palmer
Observer Email Address:	carl.jones@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	27-Jan-2018
Observation Time:	10:00
Observation Close Date:	16-Jul-2018
Details of safety observation:	While fusing a purge tee after 30 seconds there was smoke and the fusion stopped.
Immediate action taken:	I then took the top tee of the main as it was still warm and gave it to Tommy Richards to send back for investigation. This was fused to the time on the top tee kept clean and dry and not over scrapped. Where the top tee was I also soap tested it while Tommy Richards was there. You are allowed 10% wall thickness to the pipe or it has to be cut out and it was less and it was ok when soap tested he also spoke to Paul x Morgan about this.
Supporting Information:	
Feedback required?:	No