

Originator:	
Date Created:	28-Feb-2019
Business Unit:	E&I Solutions
Business Group:	Eastern US & Latin America
Project/Office:	United States - East
Site/Office Name:	Kennesaw, GA
Home or Work Related Observation?:	Home
Exact Location or Project of Act/Condition/Safe Behaviour:	Cartersville, GA
Observation Type:	Safe Behaviour
Observer Name:	Jason Muhlbauer
Observer Email Address:	jason.muhlbauer@gmail.com
Stakeholder:	Wood
Observation Date:	28-Feb-2019
Observation Time:	08:30
Observation Close Date:	28-Feb-2019
Observation Category:	Travel and Safety away from the office Transportation
Name of Individual or Team:	Jason Muhlbauer
Details of safety observation:	I noticed a very sharp dip in the road inside my subdivision around a manhole cover. I realized that the asphalt had sunk down about 6 to 8 inches within the past 2 weeks from all of the rain. The depression is clearly revealing eroding ground beneath, possibly even a sinkhole.
Immediate action taken:	I informed my HOA of the unsafe road condition so it doesn't pose a greater future threat.
Supporting Information:	
Feedback required?:	No