

<b>Observation Number:</b>	202232826
<b>Originator:</b>	
<b>Date Created:</b>	19-May-2022
<b>Business Unit:</b>	Operations
<b>Business Group:</b>	Americas
<b>Project/Office:</b>	O&M South (C&M) – ExxonMobil
<b>Sub Business Group:</b>	US South
<b>Site/Office Name:</b>	Exxon Baytown BOP
<b>Work Related or Non-Work Related Observation?:</b>	Work Related
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	BOPX
<b>Observation Type:</b>	Safe Behaviour
<b>Observer Name:</b>	Luis Guerrero
<b>Observer Email Address:</b>	Luis.guerrero@exxonmobil.com
<b>Stakeholder:</b>	Wood
<b>Observation Date:</b>	17-May-2022
<b>Observation Time:</b>	01:45
<b>Observation Close Date:</b>	19-May-2022
<b>Observation Category:</b>	Procedures and Instructions Followed / Not Followed
<b>Name of Individual or Team:</b>	Maintenance
<b>Details of safety observation:</b>	Work was being performed on a second level deck, workers ensured no one would enter the worksite by barricading off surrounding area and using approved bolt bags to carry tools up.
<b>Immediate action taken:</b>	Proper steps were taken to ensure the safety of others and themselves.
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No