

| | |
|-------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Observation Number: | 201900941 |
| Originator: | |
| Date Created: | 23-Jan-2019 |
| Business Unit: | TCS |
| Business Group: | E&I Americas |
| Project/Office: | EIA United States - West |
| Service Line: | Americas |
| Site/Office Name: | Houston, TX |
| Work Related or Non-Work Related Observation?: | Work Related |
| Exact Location or Project of Act/Condition/Safe Behaviour: | BP side of the INEOS Wastewater Pipeline project. Unsafe acts. Contractor moving a 30 ft section drill pipe with a backhoe without a tag line; texting while stand in from of moving heavy equipment; walking under backhoe bucket; and walk under backhoe arm |
| Observation Type: | Unsafe Act |
| Observer Name: | Thompson, Van |
| Observer Email Address: | van.thompson@woodplc.com |
| Stakeholder: | Contractor |
| Observation Date: | 15-Jan-2019 |
| Observation Time: | 10:00 |
| Observation Close Date: | 28-Jan-2019 |
| Observation Category: | Contractor Site safety Safety awareness & behaviour |
| Details of safety observation: | These incidents happened over several days starting on the 15th and concluding on the 17. |
| Immediate action taken: | Went to Laney Hse representative and expressed my concerns about the use of tag line. V&V by Pam Krueger and I and tag lines were being used. Standing with Laney HSE rep watching an excavation needed for placement of the horizontal drill rig. The rig representative working for Laney was texting while standing in front of a moving backhoe, walked under the backhoe bucket and the under the backhoe arm. The Laney HSE rep spoke with the rig rep and the behavior stopped. |
| Supporting Information: | |
| Feedback required?: | No |