

<b>Observation Number:</b>	201816987
<b>Originator:</b>	
<b>Date Created:</b>	13-Nov-2018
<b>Business Unit:</b>	AS EAAA
<b>Business Group:</b>	Capital Projects EAAA
<b>Project/Office:</b>	SPIN - CONTRAST MEDIA PLANT EXPANSION
<b>Service Line:</b>	SERC
<b>Site/Office Name:</b>	Spin- CMPE Site
<b>Work Related or Non-Work Related Observation?:</b>	Work Related
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	B7 piano terra 4ta campata
<b>Observation Type:</b>	Unsafe Act
<b>Observer Name:</b>	sergi domenico
<b>Observer Email Address:</b>	domenico.sergi@woodplc.com
<b>Stakeholder:</b>	Client
<b>Observation Date:</b>	12-Nov-2018
<b>Observation Time:</b>	07:45
<b>Observation Close Date:</b>	06-Dec-2018
<b>Observation Category:</b>	Work Environment Traffic routes and parking areas
<b>Details of safety observation:</b>	la canale di HVAC istallata nel progetto al piano terra, risulta essere stata urtata e danneggiata da un muletto il quale gli ha danneggiato la coibentazione .
<b>Immediate action taken:</b>	segnalato. nessuno presente al momento dell'osservazione.
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No