

|   |  |
|---|--|
| <b>Observation Number:</b>  | 201809732  |
| <b>Originator:</b>  |  |
| <b>Date Created:</b>  | 11-Jul-2018  |
| <b>Business Unit:</b>   | AS EAAA  |
| <b>Business Group:</b>  | Operations Services Europe & Africa  |
| <b>Project/Office:</b>  | Western Gas Alliance   |
| <b>Service Line:</b>  | Transmission & Distribution  |
| <b>Site/Office Name:</b>  | Western Gas Alliance 1855005/6   |
| <b>Work Related or Non-Work Related Observation?:</b>             | Work Related   |
| <b>Exact Location or Project of Act/Condition/Safe Behaviour:</b> | lougher place, bridgend  |
| <b>Observation Type:</b>  | Unsafe Condition   |
| <b>Observer Name:</b>   | Jeremy Hill  |
| <b>Observer Email Address:</b>                                    | trevor.clark@wwutilities.co.uk   |
| <b>Stakeholder:</b>   | Wood   |
| <b>Observation Date:</b>  | 01-Feb-2018  |
| <b>Observation Time:</b>  | 14:00  |
| <b>Observation Close Date:</b>                                    |  |
| <b>Details of safety observation:</b>                             | ISL:team turned up to reinstate sch 4 works 6000395323, no protection left to protect excavation |
| <b>Immediate action taken:</b>                                    | team reinstaeted concrete patch in rapid set, touch dry in around 15mins before they left.       |
| <b>Supporting Information:</b>                                    |  |
| <b>Feedback required?:</b>  | No   |
| <b>Comments from Reviewer</b>                                     |  |
| <b>Cancel Comments:</b>   | Not Wood related   |