

| | |
|---|--|
| Observation Number: | 202226013 |
| Originator: | |
| Date Created: | 19-Apr-2022 |
| Business Unit: | Operations |
| Business Group: | Americas |
| Project/Office: | O&M South (C&M) – ExxonMobil |
| Sub Business Group: | US South |
| Site/Office Name: | Exxon Baytown BOP |
| Work Related or Non-Work Related Observation?: | Work Related |
| Exact Location or Project of Act/Condition/Safe Behaviour: | Train 2 |
| Observation Type: | Safe Condition |
| Observer Name: | Luis Guerrero |
| Observer Email Address: | luis.guerrero@exxonmobil.com |
| Stakeholder: | Wood |
| Observation Date: | 18-Apr-2022 |
| Observation Time: | 03:00 |
| Observation Close Date: | 19-Apr-2022 |
| Observation Category: | Work Environment Fire & Fire prevention |
| Details of safety observation: | There was cutting, grinding and welding being performed on a valve and when I reached the worksite the proper percussions were taken. The fire watch was alert and extinguisher was at arms length, the area where the work was being performed was covered to avoid sparks from escaping and the proper ppe was utilized. |
| Immediate action taken: | Proper steps were taking to ensure there would not be a release in sparks but in case that happened, fire watch was ready to act. |
| Supporting Information: | |
| Feedback required?: | No |