

Observation Number:	202226809
Originator:	
Date Created:	22-Apr-2022
Business Unit:	Operations
Business Group:	Americas
Project/Office:	O&M South (C&M) – ExxonMobil
Sub Business Group:	US South
Site/Office Name:	Exxon Baytown BOP
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	Train 2
Observation Type:	Safe Behaviour
Observer Name:	Luis Guerrero
Observer Email Address:	luisguerrero1109@gmail.com
Stakeholder:	Wood
Observation Date:	21-Apr-2022
Observation Time:	01:30
Observation Close Date:	22-Apr-2022
Observation Category:	Contractor Site safety Barrier / Segregation
Name of Individual or Team:	Majors
Details of safety observation:	The unit we are working (Train 2) had some gaps in between the hard barricade due to material being moved in and out, when the material was safely moved in, the workers would place the barricade back in place with no gaps as to no allow anyone who didn't need to be inside access.
Immediate action taken:	The barricade was put back as needed when material was dropped off. Proper management was taken.
Supporting Information:	
Feedback required?:	No