

<b>Observation Number:</b>	201808429
<b>Originator:</b>	
<b>Date Created:</b>	24-Jun-2018
<b>Business Unit:</b>	AS EAAA
<b>Business Group:</b>	Operations Services Europe & Africa
<b>Project/Office:</b>	Western Gas Alliance
<b>Service Line:</b>	Transmission & Distribution
<b>Site/Office Name:</b>	Western Gas Alliance 1855005/6
<b>Home or Work Related Observation?:</b>	Work
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	Clifford Ave Kingswells Torquay
<b>Observation Type:</b>	Unsafe Condition
<b>Observer Name:</b>	Jason Miller
<b>Observer Email Address:</b>	john.dowson@wwutilities.co.uk
<b>Stakeholder:</b>	Wood
<b>Observation Date:</b>	17-Jan-2018
<b>Observation Time:</b>	10:30
<b>Observation Close Date:</b>	27-Jun-2018
<b>Details of safety observation:</b>	Jason Miller site visit :Team are trenching down the rd they have crossed a drive way , the team have used 3 heavy duty boards and pushed them together to allow vehicle access to the drive way
<b>Immediate action taken:</b>	Jason told the team to remove the boards and barrier off the trench and to inform the customer to leave the car off the drive way . FLM have been told to order rd plates and for them to be put in place
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No