

| | |
|---|--|
| Observation Number: | 201902049 |
| Originator: | |
| Date Created: | 12-Feb-2019 |
| Business Unit: | Consulting |
| Business Group: | Resilient Environments |
| Project/Office: | RE - West US & LATAM |
| Sub Business Group: | Americas |
| Site/Office Name: | Carlsbad Brine Well Remediation |
| Work Related or Non-Work Related Observation?: | Work Related |
| Exact Location or Project of Act/Condition/Safe Behaviour: | Drilling Rig being used onsite |
| Observation Type: | Unsafe Act |
| Observer Name: | Matthew Magill |
| Observer Email Address: | matthew.magill@woodplc.com |
| Stakeholder: | Wood |
| Observation Date: | 10-Feb-2019 |
| Observation Time: | 14:15 |
| Observation Close Date: | 12-Feb-2019 |
| Observation Category: | Contractor Site safety Safety awareness & behaviour |
| Details of safety observation: | 3rd party driller's hand climbed onto drill rig to fix hose on drive head. Began to climb up mast to reach the hose on drive head. |
| Immediate action taken: | Instructed the driller's hand that he cannot climb up things without fall protection/harness or tied off ladder. Driller lowered the drive head to a workable height from the rig floor. |
| Supporting Information: | |
| Feedback required?: | No |