

<b>Observation Number:</b>	201809247
<b>Originator:</b>	
<b>Date Created:</b>	03-Jul-2018
<b>Business Unit:</b>	AS EAAA
<b>Business Group:</b>	Operations Services Europe & Africa
<b>Project/Office:</b>	Western Gas Alliance
<b>Sub Business Group:</b>	Transmission & Distribution
<b>Site/Office Name:</b>	Western Gas Alliance 1855005/6
<b>Work Related or Non-Work Related Observation?:</b>	Work Related
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	Station inn Nantgarw Road Caerphilly
<b>Observation Type:</b>	Unsafe Condition
<b>Observer Name:</b>	Ian Palmer
<b>Observer Email Address:</b>	carl.jones@wwutilities.co.uk
<b>Stakeholder:</b>	Wood
<b>Observation Date:</b>	27-Jan-2018
<b>Observation Time:</b>	10:00
<b>Observation Close Date:</b>	16-Jul-2018
<b>Details of safety observation:</b>	While fusing a purge tee after 30 seconds there was smoke and the fusion stopped.
<b>Immediate action taken:</b>	I then took the top tee of the main as it was still warm and gave it to Tommy Richards to send back for investigation. This was fused to the time on the top tee kept clean and dry and not over scrapped. Where the top tee was I also soap tested it while Tommy Richards was there. You are allowed 10% wall thickness to the pipe or it has to be cut out and it was less and it was ok when soap tested he also spoke to Paul x Morgan about this.
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No