

| | |
|---|--|
| Observation Number: | 201810277 |
| Originator: | |
| Date Created: | 18-Jul-2018 |
| Business Unit: | AS EAAA |
| Business Group: | Operations Services Europe & Africa |
| Project/Office: | Western Gas Alliance |
| Sub Business Group: | Transmission & Distribution |
| Site/Office Name: | Western Gas Alliance 1855005/6 |
| Work Related or Non-Work Related Observation?: | Work Related |
| Exact Location or Project of Act/Condition/Safe Behaviour: | Park View , Brynmawr |
| Observation Type: | Unsafe Condition |
| Observer Name: | James Osborne |
| Observer Email Address: | carl.jones@wwutilities.co.uk |
| Stakeholder: | Wood |
| Observation Date: | 02-May-2018 |
| Observation Time: | 08:15 |
| Observation Close Date: | 12-Sep-2018 |
| Details of safety observation: | Overnight part of connection excavation has become unstable (previously deemed stable via RAMS) and fallen into excavation and onto gas main . No damage |
| Immediate action taken: | FLM instructed team to make safe , re - view RAMS form and batter back excavation |
| Supporting Information: | |
| Feedback required?: | No |