

| | |
|---|---|
| Observation Number: | 201905813 |
| Originator: | |
| Date Created: | 27-Mar-2019 |
| Business Unit: | Asset Solutions Americas |
| Business Group: | Downstream & Chemicals |
| Project/Office: | US & LATAM - Houston Office |
| Service Line: | US & Latin America |
| Site/Office Name: | US & LATAM - Houston Office |
| Home or Work Related Observation?: | Work |
| Exact Location or Project of Act/Condition/Safe Behaviour: | Celanese Bishop Facility |
| Observation Type: | Unsafe Condition |
| Observer Name: | Ernest Ortega |
| Observer Email Address: | ernest.ortega_contractor@celanese.com |
| Stakeholder: | Wood |
| Observation Date: | 27-Mar-2019 |
| Observation Time: | 14:00 |
| Observation Close Date: | 28-Mar-2019 |
| Observation Category: | Work Environment Pedestrian routes (floors, stairs etc.) |
| Details of safety observation: | Light rain and the metal stairs and handrails were wet and slippery |
| Immediate action taken: | Took extra precaution not to slip. |
| Supporting Information: | |
| Feedback required?: | No |