

|   |  |
|---|--|
| <b>Observation Number:</b>  | 201919504  |
| <b>Originator:</b>  |  |
| <b>Date Created:</b>  | 04-Aug-2019  |
| <b>Business Unit:</b>   | AS EAAA  |
| <b>Business Group:</b>  | Operations Services Asia Pac   |
| <b>Project/Office:</b>  | BSP Facilities Rejuvenation Project  |
| <b>Service Line:</b>  | SEEA   |
| <b>Site/Office Name:</b>  | BSP Facilities - Offshore  |
| <b>Home or Work Related Observation?:</b>                         | Work   |
| <b>Exact Location or Project of Act/Condition/Safe Behaviour:</b> | GP spider deck   |
| <b>Observation Type:</b>  | Unsafe Condition   |
| <b>Observer Name:</b>   | Arnel Balita   |
| <b>Observer Email Address:</b>                                    | eric.roth@woodplc.com  |
| <b>Stakeholder:</b>   | Wood   |
| <b>Observation Date:</b>  | 04-Aug-2019  |
| <b>Observation Time:</b>  | 07:30  |
| <b>Observation Close Date:</b>                                    | 08-Aug-2019  |
| <b>Observation Category:</b>                                      | Contractor Site safety<br>Housekeeping   |
| <b>Details of safety observation:</b>                             | while dismantling the scaffolding, noticed that alot of left materials on the scaffolding platform |
| <b>Immediate action taken:</b>                                    | We secure the material and inform the person responsible.  |
| <b>Supporting Information:</b>                                    |  |
| <b>Feedback required?:</b>  | No   |