

<b>Observation Number:</b>	201809250
<b>Originator:</b>	
<b>Date Created:</b>	03-Jul-2018
<b>Business Unit:</b>	AS EAAA
<b>Business Group:</b>	Operations Services Europe & Africa
<b>Project/Office:</b>	Western Gas Alliance
<b>Sub Business Group:</b>	Transmission & Distribution
<b>Site/Office Name:</b>	Western Gas Alliance 1855005/6
<b>Work Related or Non-Work Related Observation?:</b>	Work Related
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	Nantgarw Road Caerphilly
<b>Observation Type:</b>	Unsafe Condition
<b>Observer Name:</b>	Ian Palmer
<b>Observer Email Address:</b>	carl.jones@wwutilities.co.uk
<b>Stakeholder:</b>	Wood
<b>Observation Date:</b>	27-Jan-2018
<b>Observation Time:</b>	09:15
<b>Observation Close Date:</b>	16-Jul-2018
<b>Details of safety observation:</b>	Went to fuse a 75 cap end and there was no copper connection point on the cap end to connect the leads. This came from the Stores and still in the bag. Again very poor quality fittings.
<b>Immediate action taken:</b>	T/L gave it to Tommy Richards to send back for investigation.
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No