

<b>Observation Number:</b>	201902049
<b>Originator:</b>	
<b>Date Created:</b>	12-Feb-2019
<b>Business Unit:</b>	E&I Solutions
<b>Business Group:</b>	Western US
<b>Project/Office:</b>	United States - West
<b>Site/Office Name:</b>	Carlsbad Brine Well Remediation
<b>Home or Work Related Observation?:</b>	Work
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	Drilling Rig being used onsite
<b>Observation Type:</b>	Unsafe Act
<b>Observer Name:</b>	Matthew Magill
<b>Observer Email Address:</b>	matthew.magill@woodplc.com
<b>Stakeholder:</b>	Wood
<b>Observation Date:</b>	10-Feb-2019
<b>Observation Time:</b>	14:15
<b>Observation Close Date:</b>	12-Feb-2019
<b>Observation Category:</b>	Contractor Site safety Safety awareness & behaviour
<b>Details of safety observation:</b>	3rd party driller's hand climbed onto drill rig to fix hose on drive head. Began to climb up mast to reach the hose on drive head.
<b>Immediate action taken:</b>	Instructed the driller's hand that he cannot climb up things without fall protection/harness or tied off ladder. Driller lowered the drive head to a workable height from the rig floor.
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No