| | |
|---|---|
| **Originator:** | |
| **Date Created:** | 11-Jan-2019 |
| **Business Unit:** | AS EAAA |
| **Business Group:** | Capital Projects EAAA |
| **Project/Office:** | PREEM |
| **Service Line:** | NEMEA |
| **Site/Office Name:** | Amec FW / VGO Project PREEM |
| **Home or Work Related Observation?:** | Work |
| **Exact Location or Project of Act/Condition/Safe Behaviour:** | West side Pipe rack top floor. |
| **Observation Type:** | Unsafe Condition |
| **Observer Name:** | Kolliboina, Vamsi |
| **Observer Email Address:** | vamsi.kolliboina@woodplc.com |
| **Stakeholder:** | Wood |
| **Observation Date:** | 11-Jan-2019 |
| **Observation Time:** | 10:30 |
| **Observation Close Date:** | 05-Feb-2019 |
| **Observation Category:** | Work Environment<br>Pedestrian routes (floors, stairs etc.) |
| **Details of safety observation:** | The tarpaulin sheet spread on the top floor of the rack for protection from blasting is not secure in places and is coming off and can be a trip hazard for the workforce walking on it. |
| **Immediate action taken:** | |
| **Supporting Information:** | |
| **Feedback required?:** | No |

**Reasons for Amendment**

| Comment | Entered By | Date Entered |
|---|---|---|
| Obs name | Paul Harrington | 05-April-2019 11:23 |