

Observation Number:	201902052
Originator:	
Date Created:	12-Feb-2019
Business Unit:	TCS
Business Group:	E&I Americas
Project/Office:	EIA United States - West
Service Line:	Americas
Site/Office Name:	Carlsbad Brine Well Remediation
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	Drill rig floor
Observation Type:	Unsafe Act
Observer Name:	Matthew Magill
Observer Email Address:	matthew.magill@woodplc.com
Stakeholder:	Wood
Observation Date:	11-Feb-2019
Observation Time:	08:30
Observation Close Date:	12-Feb-2019
Observation Category:	Contractor Site safety Safety awareness & behaviour
Details of safety observation:	While tripping in, driller's hand placed themselves between drill rod and the wellhead at which the drill rod was attached to.
Immediate action taken:	Informed the driller's hand of their improper body placement and explained the potential for them to be caught between objects.
Supporting Information:	
Feedback required?:	No