

<b>Originator:</b>	
<b>Date Created:</b>	18-Jul-2018
<b>Business Unit:</b>	AS EAAA
<b>Business Group:</b>	Operations Services Europe & Africa
<b>Project/Office:</b>	Western Gas Alliance
<b>Service Line:</b>	Transmission & Distribution
<b>Site/Office Name:</b>	Western Gas Alliance 1855005/6
<b>Home or Work Related Observation?:</b>	Work
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	Newport Stores, Large meeting room.
<b>Observation Type:</b>	Unsafe Condition
<b>Observer Name:</b>	Paul Breakey
<b>Observer Email Address:</b>	chris.wilde@amecfw.com
<b>Stakeholder:</b>	Wood
<b>Observation Date:</b>	07-Mar-2018
<b>Observation Time:</b>	09:45
<b>Observation Close Date:</b>	
<b>Details of safety observation:</b>	Yet again 3 extension leads haven't been PAT tested for electrical safety. 1 of the plugs has a sticker dated 2013
<b>Immediate action taken:</b>	
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No
<b>Comments from Reviewer</b>	
<b>Cancel Comments:</b>	Not wood related