

<b>Observation Number:</b>	201900420	
<b>Originator:</b>		
<b>Date Created:</b>	11-Jan-2019	
<b>Business Unit:</b>	AS EAAA	
<b>Business Group:</b>	Capital Projects EAAA	
<b>Project/Office:</b>	PREEM	
<b>Service Line:</b>	NEMEA	
<b>Site/Office Name:</b>	Amec FW / VGO Project PREEM	
<b>Work Related or Non-Work Related Observation?:</b>	Work Related	
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	West side Pipe rack top floor.	
<b>Observation Type:</b>	Unsafe Condition	
<b>Observer Name:</b>	Kolliboina, Vamsi	
<b>Observer Email Address:</b>	vamsi.kolliboina@woodplc.com	
<b>Stakeholder:</b>	Wood	
<b>Observation Date:</b>	11-Jan-2019	
<b>Observation Time:</b>	10:30	
<b>Observation Close Date:</b>	05-Feb-2019	
<b>Observation Category:</b>	Work Environment Pedestrian routes (floors, stairs etc.)	
<b>Details of safety observation:</b>	The tarpaulin sheet spread on the top floor of the rack for protection from blasting is not secure in places and is coming off and can be a trip hazard for the workforce walking on it.	
<b>Immediate action taken:</b>		
<b>Supporting Information:</b>		
<b>Feedback required?:</b>	No	
<b>Reasons for Amendment</b>		
<b>Comment</b>	<b>Entered By</b>	<b>Date Entered</b>
Obs name	Paul Harrington	05-April-2019 11:23