

<b>Observation Number:</b>	201925537
<b>Originator:</b>	
<b>Date Created:</b>	26-Sep-2019
<b>Business Unit:</b>	TCS
<b>Business Group:</b>	Mining & Minerals
<b>Project/Office:</b>	Kemerton Project
<b>Service Line:</b>	APAC
<b>Site/Office Name:</b>	Kemerton Project Site
<b>Work Related or Non-Work Related Observation?:</b>	Work Related
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	Train One Hydromet Area
<b>Observation Type:</b>	Safe Behaviour
<b>Observer Name:</b>	Stephen Andrews
<b>Observer Email Address:</b>	steve.andrews3@woodplc.com
<b>Stakeholder:</b>	Wood
<b>Observation Date:</b>	26-Sep-2019
<b>Observation Time:</b>	08:30
<b>Observation Close Date:</b>	26-Sep-2019
<b>Observation Category:</b>	Work Environment Pedestrian routes (floors, stairs etc.)
<b>Name of Individual or Team:</b>	Civmec
<b>Details of safety observation:</b>	Lifting in pre-cast concrete sumps, hole in sump which pedestrians have the potential to fall were covered to protect from falling in prior to installation.
<b>Immediate action taken:</b>	Good initiative by contractor to identify the potential hazard and take steps to mitigate hazard
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No