

Observation Number:	201920867
Originator:	
Date Created:	15-Aug-2019
Business Unit:	TCS
Business Group:	Automation & Control
Project/Office:	Houston (A&C)
Service Line:	Americas
Site/Office Name:	Houston (A&C) Wood/Internal (onshore)
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	Horseshoe Building Back Parking Lot near Door "P"
Observation Type:	Unsafe Condition
Observer Name:	Leary, Mike
Observer Email Address:	Mike.Leary@woodplc.com
Stakeholder:	Wood
Observation Date:	12-Aug-2019
Observation Time:	08:00
Observation Close Date:	15-Aug-2019
Observation Category:	Work Environment Housekeeping
Details of safety observation:	On Monday, after reverse-parking my SUV in parking space to the right of door "P" (facing door), on way into building I noticed screws in the parking space to the left of door "P". Thursday morning, I discover a screw in the shoulder of one of my tires, necessitating replacement of the tire as it was not repairable. Fortunately, the screw was discovered before a significant loss of tire pressure and the tire has road hazard coverage for the replacement. I checked both parking spaces this morning and did not see any remaining screws in them, but there are a couple screws underneath the porch.
Immediate action taken:	Picked up visible screws when noticed, before someone could park in affected space.
Supporting Information:	
Feedback required?:	No