

<b>Observation Number:</b>	201809249
<b>Originator:</b>	
<b>Date Created:</b>	03-Jul-2018
<b>Business Unit:</b>	AS EAAA
<b>Business Group:</b>	Operations Services Europe & Africa
<b>Project/Office:</b>	Western Gas Alliance
<b>Service Line:</b>	Transmission & Distribution
<b>Site/Office Name:</b>	Western Gas Alliance 1855005/6
<b>Work Related or Non-Work Related Observation?:</b>	Work Related
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	Ridge rd Torquay
<b>Observation Type:</b>	Unsafe Act
<b>Observer Name:</b>	Chris Wilde
<b>Observer Email Address:</b>	john.dowson@wwutilities.co.uk
<b>Stakeholder:</b>	Wood
<b>Observation Date:</b>	29-Jan-2018
<b>Observation Time:</b>	12:30
<b>Observation Close Date:</b>	
<b>Details of safety observation:</b>	Chris Wilde attended site to do Cat / Genny down load the. T/L already marked the position of the HV cable but the Cat / Genny assessment showed the markings were incorrect . The T/L was aware that he could not carry out until he passed his assessment
<b>Immediate action taken:</b>	T/L failed , he was given a TBT before he could carry out on site
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No
<b>Comments from Reviewer</b>	
<b>Cancel Comments:</b>	Not wood related