

<b>Observation Number:</b>	201810278
<b>Originator:</b>	
<b>Date Created:</b>	18-Jul-2018
<b>Business Unit:</b>	AS EAAA
<b>Business Group:</b>	Operations Services Europe & Africa
<b>Project/Office:</b>	Western Gas Alliance
<b>Service Line:</b>	Transmission & Distribution
<b>Site/Office Name:</b>	Western Gas Alliance 1855005/6
<b>Home or Work Related Observation?:</b>	Work
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	Park View , Brynmawr
<b>Observation Type:</b>	Unsafe Condition
<b>Observer Name:</b>	James Osborne
<b>Observer Email Address:</b>	carl.jones@wwutilities.co.uk
<b>Stakeholder:</b>	Wood
<b>Observation Date:</b>	03-May-2018
<b>Observation Time:</b>	09:30
<b>Observation Close Date:</b>	12-Sep-2018
<b>Details of safety observation:</b>	New vac ex driver on site . All paper work and risk assessments completed . While operating power boom caught 3/4" gas service which team cut off and made safe . Team subsequently relayed service as part of planned works .
<b>Immediate action taken:</b>	FLM ( James Osborne) had a discussion with Vac Ex driver ( Chris) regarding dangers of power loom and to pace himself with team . Good feedback and interaction . No further action deemed required and logged for records only
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No