

<b>Observation Number:</b>	201808470
<b>Originator:</b>	
<b>Date Created:</b>	25-Jun-2018
<b>Business Unit:</b>	AS EAAA
<b>Business Group:</b>	Operations Services Europe & Africa
<b>Project/Office:</b>	Western Gas Alliance
<b>Sub Business Group:</b>	Transmission & Distribution
<b>Site/Office Name:</b>	Western Gas Alliance 1855005/6
<b>Work Related or Non-Work Related Observation?:</b>	Work Related
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	Gelli Cottages Cymmer Port Talbot
<b>Observation Type:</b>	Unsafe Condition
<b>Observer Name:</b>	John Royals
<b>Observer Email Address:</b>	steve.edwards@wwutilities.co.uk
<b>Stakeholder:</b>	Wood
<b>Observation Date:</b>	18-Jan-2018
<b>Observation Time:</b>	08:15
<b>Observation Close Date:</b>	27-Jun-2018
<b>Details of safety observation:</b>	From approximately the start of the winter time??? The team have been experiencing issues with the stone it's been soaking wet causing puddles whilst whacking the stone trying to make it stick.
<b>Immediate action taken:</b>	The team had to send the stone back yesterday and it was un- useable
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	No