

<b>Observation Number:</b>	201904156	
<b>Originator:</b>		
<b>Date Created:</b>	12-Mar-2019	
<b>Business Unit:</b>	AS EAAA	
<b>Business Group:</b>	Capital Projects EAAA	
<b>Project/Office:</b>	South Africa Home Office	
<b>Service Line:</b>	NEMEA	
<b>Site/Office Name:</b>	Midrand Office	
<b>Work Related or Non-Work Related Observation?:</b>	Work Related	
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	The smoking area located by block A under thatch roof area.	
<b>Observation Type:</b>	Unsafe Condition	
<b>Observer Name:</b>	Rene	
<b>Observer Email Address:</b>	rene.bosman@woodplc.com	
<b>Stakeholder:</b>	Wood	
<b>Observation Date:</b>	12-Mar-2019	
<b>Observation Time:</b>	11:00	
<b>Observation Close Date:</b>	18-Mar-2019	
<b>Observation Category:</b>	Work Environment Furniture and Work equipment	
<b>Details of safety observation:</b>	The cement table top is off centered and may fall to the one side.	
<b>Immediate action taken:</b>	Observer called maintenance to investigate and move the table top back to the center.	
<b>Supporting Information:</b>		
<b>Feedback required?:</b>	No	
<b>Reasons for Amendment</b>		
<b>Comment</b>	<b>Entered By</b>	<b>Date Entered</b>
Observation has been closed out and hazard has been satisfactorily addressed	Daniel Roodt	18-March-2019 09:41