

Observation Number:	201808476
Originator:	
Date Created:	25-Jun-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Sub Business Group:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	Thomson Avenue, Canton
Observation Type:	Unsafe Condition
Observer Name:	John Morgan
Observer Email Address:	carl.jones@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	24-Jan-2018
Observation Time:	08:15
Observation Close Date:	27-Jun-2018
Details of safety observation:	Team came to site this morning and all the barriers were placed in the middle off the rd blocking the traffic and some were down (ref children in the area)
Immediate action taken:	Team replaced barriers and made site safe
Supporting Information:	
Feedback required?:	No