

Observation Number:	201808472
Originator:	
Date Created:	25-Jun-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	Barry Jct Wyndam St
Observation Type:	Safe Behaviour
Observer Name:	John Ross
Observer Email Address:	trevor.clark@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	23-Jan-2018
Observation Time:	14:15
Observation Close Date:	27-Jun-2018
Name of Individual or Team:	Reinstatement
Details of safety observation:	ISL - Intervention: Team member left a pick on the floor by a team member this was noticed by the T/L straight away
Immediate action taken:	T/L pulled team member to one side and explained danger / trip hazard keeping safe public and team members and told him the site has to remain safe at all times and tools to be put in stored in a correct place when not being used
Supporting Information:	
Feedback required?:	No