

|   |  |
|---|--|
| <b>Observation Number:</b>  | 201810250  |
| <b>Originator:</b>  |  |
| <b>Date Created:</b>  | 18-Jul-2018  |
| <b>Business Unit:</b>   | AS EAAA  |
| <b>Business Group:</b>  | Operations Services Europe & Africa                    |
| <b>Project/Office:</b>  | Western Gas Alliance                                   |
| <b>Sub Business Group:</b>  | Transmission & Distribution                            |
| <b>Site/Office Name:</b>  | Western Gas Alliance 1855005/6                         |
| <b>Work Related or Non-Work Related Observation?:</b>             | Work Related   |
| <b>Exact Location or Project of Act/Condition/Safe Behaviour:</b> | Llandarcy Stores                                       |
| <b>Observation Type:</b>  | Unsafe Condition                                       |
| <b>Observer Name:</b>   | Craig Catterson  |
| <b>Observer Email Address:</b>                                    | steve.edwards@wwutilities.co.uk                        |
| <b>Stakeholder:</b>   | Wood   |
| <b>Observation Date:</b>  | 08-Mar-2018  |
| <b>Observation Time:</b>  | 11:00  |
| <b>Observation Close Date:</b>                                    | 18-Jul-2018  |
| <b>Details of safety observation:</b>                             | Light switch in stores room chipped                    |
| <b>Immediate action taken:</b>                                    | Reported to Jade who is getting the light switch fixed |
| <b>Supporting Information:</b>                                    |  |
| <b>Feedback required?:</b>  | No   |