

Observation Number:	201810271
Originator:	
Date Created:	18-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Sub Business Group:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	Heol Nant Garw Methyr Tydfil
Observation Type:	Unsafe Condition
Observer Name:	Peter Tyler
Observer Email Address:	carl.jones@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	12-Apr-2018
Observation Time:	08:45
Observation Close Date:	13-Aug-2018
Details of safety observation:	1 x footpath on site and FLM noticed No walk ways
Immediate action taken:	Walk ways have now been put in place for the safety of the public
Supporting Information:	
Feedback required?:	No