

Observation Number:	201809624
Originator:	
Date Created:	09-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	Maindy Rd Cowbridge
Observation Type:	Unsafe Act
Observer Name:	Christopher John
Observer Email Address:	trevor.clark@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	26-Jan-2018
Observation Time:	13:45
Observation Close Date:	
Details of safety observation:	Intervention : Team digging out kerbs leant the pick against the wall then noticed it had fallen on the footpath
Immediate action taken:	The pick was uplifted straight away and put safe within the barrier system
Supporting Information:	
Feedback required?:	No
Comments from Reviewer	
Cancel Comments:	Not Wood related