

Observation Number:	201903409
Originator:	
Date Created:	28-Feb-2019
Business Unit:	Projects
Business Group:	Conventional Energy
Project/Office:	Reading Office
Sub Business Group:	Europe & Africa
Site/Office Name:	Reading Office
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	SP0E Corporate area
Observation Type:	Unsafe Condition
Observer Name:	Littleford, Mark
Observer Email Address:	mark.littleford@woodplc.com
Stakeholder:	Wood
Observation Date:	28-Feb-2019
Observation Time:	10:00
Observation Close Date:	
Observation Category:	Work Environment Pedestrian routes (floors, stairs etc.)
Details of safety observation:	the ramp is hidden by the carpet colour and local lighting, causing one of my colleagues to fall down the ramp, jarring his back.
Immediate action taken:	
Supporting Information:	Heart.docx
Feedback required?:	Yes
Comments from Reviewer	
Cancel Comments:	Incident represents an slip / trip.



When entering the slope is visible and there is a warning sign.



When leaving the office the ramp is hidden by lighting effect and there is no sign.