

Observation Number:	201913253
Originator:	
Date Created:	15-Jun-2019
Business Unit:	Projects
Business Group:	Process & Chemicals
Project/Office:	Kemerton Project
Sub Business Group:	Mining & Minerals
Site/Office Name:	Kemerton Project Site
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	Site wide
Observation Type:	Unsafe Condition
Observer Name:	Stephen Andrews
Observer Email Address:	steve.andrews3@woodplc.com
Stakeholder:	Contractor
Observation Date:	15-Jun-2019
Observation Time:	07:00
Observation Close Date:	17-Jun-2019
Observation Category:	Work Environment Traffic routes and parking areas
Details of safety observation:	Heavy fog covering site making it difficult to see road sign directions and other plant .
Immediate action taken:	Spoke to work group to be extra cautious when driving on site and obey speedlimits and drive to conditions until weather improves
Supporting Information:	
Feedback required?:	No