

Observation Number:	201810052
Originator:	
Date Created:	16-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	church st, usk
Observation Type:	Unsafe Act
Observer Name:	Mark Bees
Observer Email Address:	trevor.clark@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	09-Feb-2018
Observation Time:	10:15
Observation Close Date:	
Details of safety observation:	ISL:one of the team memebbers left a pick at the side of the reinstatement.
Immediate action taken:	team members asked to return tool to the rear of their vehicle for safe keeping.
Supporting Information:	
Feedback required?:	No
Comments from Reviewer	
Cancel Comments:	Not Wood related