

Observation Number:	201925537
Originator:	
Date Created:	26-Sep-2019
Business Unit:	Projects
Business Group:	Process & Chemicals
Project/Office:	Kemerton Project
Sub Business Group:	Mining & Minerals
Site/Office Name:	Kemerton Project Site
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	Train One Hydromet Area
Observation Type:	Safe Behaviour
Observer Name:	Stephen Andrews
Observer Email Address:	steve.andrews3@woodplc.com
Stakeholder:	Wood
Observation Date:	26-Sep-2019
Observation Time:	08:30
Observation Close Date:	26-Sep-2019
Observation Category:	Work Environment Pedestrian routes (floors, stairs etc.)
Name of Individual or Team:	Civmec
Details of safety observation:	Lifting in pre-cast concrete sumps, hole in sump which pedestrians have the potential to fall were covered to protect from falling in prior to installation.
Immediate action taken:	Good initiative by contractor to identify the potential hazard and take steps to mitigate hazard
Supporting Information:	
Feedback required?:	No