

| | |
|---|--|
| Observation Number: | 201809729 |
| Originator: | |
| Date Created: | 11-Jul-2018 |
| Business Unit: | AS EAAA |
| Business Group: | Operations Services Europe & Africa |
| Project/Office: | Western Gas Alliance |
| Service Line: | Transmission & Distribution |
| Site/Office Name: | Western Gas Alliance 1855005/6 |
| Work Related or Non-Work Related Observation?: | Work Related |
| Exact Location or Project of Act/Condition/Safe Behaviour: | Heol Cadifor Swansea |
| Observation Type: | Unsafe Condition |
| Observer Name: | Adam Evans |
| Observer Email Address: | steve.edwards@wwutilities.co.uk |
| Stakeholder: | Wood |
| Observation Date: | 01-Feb-2018 |
| Observation Time: | 11:45 |
| Observation Close Date: | 16-Jul-2018 |
| Details of safety observation: | 2 incidents regarding the new Sperryn emergency control valves the main tap competed and tightened by the team you would have to use a spanner with force release , but there seems to be a quarter of an inch of play in it |
| Immediate action taken: | Rang in a heart observation and will arrange for the materials to be investigated by Thomas James . Adam Evans has also taken a video and he will pass this on |
| Supporting Information: | |
| Feedback required?: | No |