

| | |
|---|---|
| Observation Number: | 201808466 |
| Originator: | |
| Date Created: | 25-Jun-2018 |
| Business Unit: | AS EAAA |
| Business Group: | Operations Services Europe & Africa |
| Project/Office: | Western Gas Alliance |
| Sub Business Group: | Transmission & Distribution |
| Site/Office Name: | Western Gas Alliance 1855005/6 |
| Work Related or Non-Work Related Observation?: | Work Related |
| Exact Location or Project of Act/Condition/Safe Behaviour: | Murgwyn jct of Heol y Felin Rwibina |
| Observation Type: | Unsafe Condition |
| Observer Name: | Dean George |
| Observer Email Address: | carl.jones@wwutilities.co.uk |
| Stakeholder: | Wood |
| Observation Date: | 19-Jan-2018 |
| Observation Time: | 12:15 |
| Observation Close Date: | 27-Jun-2018 |
| Details of safety observation: | The team lifted slabs to dig out a connection hole to locate services and found a large BT cable under the slabs near the surface that had previously been damaged and looped around the excavation . |
| Immediate action taken: | The team used the air lance to expose the cable , lifted out the BT cable whilst digging out the hold and did safe digging practice |
| Supporting Information: | |
| Feedback required?: | No |