

Observation Number:	201810605
Originator:	
Date Created:	24-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Sub Business Group:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	Cliff Terrace Burryport
Observation Type:	Unsafe Condition
Observer Name:	Joe Smiriglia
Observer Email Address:	steve.edwards@wwutilities.co.uk
Stakeholder:	Contractor
Observation Date:	18-Jul-2018
Observation Time:	09:30
Observation Close Date:	03-Oct-2018
Details of safety observation:	The team cannot get hold of the print out data on the Butt Fusion machine
Immediate action taken:	Steve Edwards will contact PSS
Supporting Information:	
Feedback required?:	No
Comments from Reviewer	
Action to be taken:	Escalated with the project as a quality/supply chain issue
Supporting Information:	
Comments from OU Admin	
Closing Comments:	Passed to project to manage locally given the contractual changes