

<b>Observation Number:</b>	201912954
<b>Originator:</b>	
<b>Date Created:</b>	11-Jun-2019
<b>Business Unit:</b>	Projects
<b>Business Group:</b>	Process & Chemicals
<b>Project/Office:</b>	Kemerton Project
<b>Sub Business Group:</b>	Mining & Minerals
<b>Site/Office Name:</b>	Kemerton Project Site
<b>Work Related or Non-Work Related Observation?:</b>	Work Related
<b>Exact Location or Project of Act/Condition/Safe Behaviour:</b>	Security Hut site entrance
<b>Observation Type:</b>	Unsafe Condition
<b>Observer Name:</b>	Stephen Andrews
<b>Observer Email Address:</b>	steve.andrews3@woodplc.com
<b>Stakeholder:</b>	3rd Party
<b>Observation Date:</b>	11-Jun-2019
<b>Observation Time:</b>	05:45
<b>Observation Close Date:</b>	14-Jun-2019
<b>Observation Category:</b>	Work Environment Pedestrian routes (floors, stairs etc.)
<b>Details of safety observation:</b>	When waiting for lift from security office to site there is no where to shelter from inclement weather
<b>Immediate action taken:</b>	
<b>Supporting Information:</b>	
<b>Feedback required?:</b>	Yes
<b>Comments from Reviewer</b>	
<b>Closing Comments:</b>	Sheltered walkways to be provided once permanent car park is installed off site.