

Observation Number:	201903762
Originator:	
Date Created:	06-Mar-2019
Business Unit:	Operations
Business Group:	Asia Pacific
Project/Office:	PSNS - SEIC TSS
Sub Business Group:	APAC West
Site/Office Name:	PSNS Office
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	5th floor emergency stairs
Observation Type:	Unsafe Act
Observer Name:	GEYER, Alexander
Observer Email Address:	Alexander.Geyer@woodplc.com
Stakeholder:	Wood
Observation Date:	06-Mar-2019
Observation Time:	16:15
Observation Close Date:	06-Mar-2019
Observation Category:	Work Environment Fire & Fire prevention
Details of safety observation:	E&I Engineer took an emergency stairs to move between floors, as was noted to move down from 8th to 5th floor.
Immediate action taken:	Intervened by advising employee that the emergency stairs should be use only in case of emergency
Supporting Information:	
Feedback required?:	No