

| | |
|---|---|
| Observation Number: | 201808476 |
| Originator: | |
| Date Created: | 25-Jun-2018 |
| Business Unit: | AS EAAA |
| Business Group: | Operations Services Europe & Africa |
| Project/Office: | Western Gas Alliance |
| Service Line: | Transmission & Distribution |
| Site/Office Name: | Western Gas Alliance 1855005/6 |
| Home or Work Related Observation?: | Work |
| Exact Location or Project of Act/Condition/Safe Behaviour: | Thomson Avenue, Canton |
| Observation Type: | Unsafe Condition |
| Observer Name: | John Morgan |
| Observer Email Address: | carl.jones@wwutilities.co.uk |
| Stakeholder: | Wood |
| Observation Date: | 24-Jan-2018 |
| Observation Time: | 08:15 |
| Observation Close Date: | 27-Jun-2018 |
| Details of safety observation: | Team came to site this morning and all the barriers were placed in the middle off the rd blocking the traffic and some were down (ref children in the area) |
| Immediate action taken: | Team replaced barriers and made site safe |
| Supporting Information: | |
| Feedback required?: | No |