

Observation Number:	201808457
Originator:	
Date Created:	25-Jun-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	Fairfield Crs Llantwit Major
Observation Type:	Unsafe Condition
Observer Name:	Gary Hathway
Observer Email Address:	trevor.clark@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	18-Jan-2018
Observation Time:	08:00
Observation Close Date:	27-Jun-2018
Details of safety observation:	ISL Intervention : Team went to site to and found the small concrete patch on site on the private had No barriers around or signs
Immediate action taken:	The team made safe filled the the concrete patch and informed the customer on the situation and to be careful
Supporting Information:	
Feedback required?:	No