

Observation Number:	201916363
Originator:	
Date Created:	12-Jul-2019
Business Unit:	Projects
Business Group:	Process & Chemicals
Project/Office:	Kemerton Project
Sub Business Group:	Mining & Minerals
Site/Office Name:	Kemerton Project Site
Work Related or Non-Work Related Observation?:	Work Related
Exact Location or Project of Act/Condition/Safe Behaviour:	Access Road into Kemerton site
Observation Type:	Safe Behaviour
Observer Name:	Stephen Andrews
Observer Email Address:	steve.andrews3@woodplc.com
Stakeholder:	Contractor
Observation Date:	08-Jul-2019
Observation Time:	11:15
Observation Close Date:	12-Jul-2019
Observation Category:	Integrity Management Hazard Evaluation & Risk Management
Name of Individual or Team:	Pinjarra Cranes
Details of safety observation:	Accessing and egressing the back of trailer to offload concrete blocks weighing 8T, Hazards were identified and addressed in a professional manner brought to the attention of Wood supervisor and discussed in detail best and safest way forward to complete task successfully
Immediate action taken:	Was impressed that crew did not take it on their own back just to climb onto trailer without thinking they shown due care and attention to the task at hand congratulated on job thought process they put in simple but affective.
Supporting Information:	
Feedback required?:	No