

Observation Number:	201810284
Originator:	
Date Created:	18-Jul-2018
Business Unit:	AS EAAA
Business Group:	Operations Services Europe & Africa
Project/Office:	Western Gas Alliance
Service Line:	Transmission & Distribution
Site/Office Name:	Western Gas Alliance 1855005/6
Home or Work Related Observation?:	Work
Exact Location or Project of Act/Condition/Safe Behaviour:	Wrexham Road Johnstown
Observation Type:	Unsafe Condition
Observer Name:	Adrian Degg
Observer Email Address:	paul.astley@wwutilities.co.uk
Stakeholder:	Wood
Observation Date:	19-May-2018
Observation Time:	15:15
Observation Close Date:	12-Sep-2018
Details of safety observation:	Excavation not protected by barriers (possible vandals)
Immediate action taken:	Re-erected around barriers around unprotected excavation
Supporting Information:	
Feedback required?:	No